

Asbestos Inspection Results (Example)

Project Name:		Chan Residence		Date of Survey:		15 Oct 07	
Address:		123 Anystreet, North Vancouver, B.C.		Survey Company:		Bob's Asbestos Consulting	
Description:		Residential (house); One Storey Rancher with an Attic		Surveyor:		Bob Smith	
Previous Renovations?		Yes, Bathroom and Kitchen (10 years ago)		Age of Structure:		45 Years	
Laboratory Name:		Asbestos Laboratories Inc		Analysis Method(s):		NIOSH Method 9002 EPA/600/R-04/004	
Area or Room (directions when facing house)	Building Materials	Sampling Location	Material Collected (sample #)	Asbestos Type and Percentage	Approximate Quantity of Asbestos		
Entry	Walls and ceiling are drywall; floor is ceramic tile	Right Wall	Drywall Mud (1)	Chrysotile 1-3%	All walls and ceiling		
Hallway	Walls are drywall; ceiling is textured; floor is carpet (concrete beneath)	Ceiling	Texture Coat (2)	Chrysotile 1-3%	All walls and ceiling		
Living Room	Walls are drywall; ceiling is textured; floor is carpet (concrete beneath)	Ceiling	Texture Coat (3) Drywall mud (4)	Chrysotile 1-3% Chrysotile 1-3%	Ceiling All walls		
Dining Room	Walls are drywall; ceiling is textured; floor is carpet (concrete beneath)	Left Wall	Drywall Mud (5)	Chrysotile 1-3%	All walls and ceiling		
Kitchen	Walls and ceiling are drywall; floor is linoleum	Right Wall Floor	Drywall Mud (6) Linoleum (7)	None None	None		
Bathroom	Walls and ceiling are drywall; floor is ceramic tile	Left Wall	Drywall Mud (8)	None	None		
Right Bedroom	Walls are drywall; ceiling is textured; floor is carpet (concrete beneath)	Ceiling	Texture Coat (9)	Chrysotile 1-3%	All walls and ceiling		
Left Bedroom	Walls are drywall; ceiling is textured; floor is carpet (concrete beneath)	Rear Wall	Drywall Mud (10)	Chrysotile 1-3%	All walls and ceiling		
Attic	Insulation is fibreglass batt with vermiculite beneath	Left Attic Right Attic	Vermiculite (11) Vermiculite (12) Vermiculite (13)	Actinolite 0.7% Actinolite 1% Actinolite 1%	Entire Attic		
Exterior	Exterior is wood; roof is composition shingles; aluminum frame windows	Roof	Shingle (14)	None	None		
Furnace		Ducting	Tape (15)	Chrysotile 30%	All Ducting		
Crawl Space	Pipe Insulation	Below kitchen	Pipe wrapping (16)	Chrysotile 35%	All crawl space piping		