



ResourceRoads Demonstration Project Incident Types on Resource Roads

These sample summaries are based on Notice of Incident reports received by WorkSafeBC. The information is preliminary and subject to change; it is published to alert employers and workers to hazards in their industry. You can sign up for free e-mail updates of summaries like these at: <http://www2.worksafebc.com/s/SubscribeNow.asp>

PRIMARY RESOURCES

Injury Type: Fatal **ID Number:** 2008158930095
Core Activity: Logging road construction **Date of Accident:** 2008-May
Location: Vancouver Island
 A driller-blaster was returning from a post-blast inspection when he was struck and pinned against the tracks of an excavator by a large log that rolled off the steep cutbank above.

Injury Type: Fatal (1 worker); minor injuries (4 workers) **ID Number:** 2008091010004
Core Activity: Tree planting **Date of Accident:** 2008-May
Location: Northern BC
 A crew cab went out of control on a gravel road. The vehicle slid into the ditch and rolled, ejecting one worker. The ejected worker was pinned under the vehicle and died. Four other workers, including one young worker, sustained minor injuries.

Injury Type: Head injury **ID Number:** 2008034450116
Core Activity: Integrated logging **Date of Accident:** 2008-Apr
Location: Central Interior
 A loaded log transporter (jeep with a wagon) was negotiating a 6 percent downhill curve on a forest service road. The truck rolled at the midpoint of the 90-degree curve.

Injury Type: Close Call **ID Number:** 2008034450044
Core Activity: Log hauling **Date of Accident:** 2008-Feb
Location: Central Interior
 On a forest service road, a loaded pole-style log transporter encountered an oncoming empty log transporter. The loaded truck drove off the travelled portion of the road. The load of logs slid forward, damaging the cab guard and cab. The empty truck was not damaged.

Injury Type: Fatal **ID Number:** 2007116110213
Core Activity: Travelling from logging camp **Date of Accident:** 2007-Sep
Location: Northern BC
 A pickup truck went out of control as it approached a bridge on a forest service road. The truck left the road and landed upside down in the river.

Injury Type: Fatal (1 worker); multiple fractures of foot and ankle, dislocated hip (1 worker) **ID Number:** 2007104070088
Core Activity: Travel on logging road **Date of Accident:** 2007-Aug
Location: Central Interior
 Two workers were driving out of the bush in a 1-ton vehicle. It skidded off a narrow portion of the logging road and rolled. The vehicle went end-over-end at least once down about 150 feet on a 78 percent slope. The workers, who were not wearing seat belts, were ejected.

Injury Type: Shoulder injury; bruises, contusions, abrasions **ID Number:** 2006155980126
Core Activity: Log loading **Date of Accident:** 2006-Jun
Location: Vancouver Island
 A rubber-tired log loader was being backed down a logging road when the road gave out on the downhill side. The loader flopped onto its side and slid 40 feet down the hill, coming to rest against two large stumps.

Injury Type: Fatal **ID Number:** 2005136970264

Core Activity: Integrated forest management **Date of Accident:** 2005-Dec

Location: Northern BC

The operator of a loaded logging truck was killed when the truck went over the bank of a forestry road and the load of logs shifted forward, crushing the cab.

Injury Type: Broken femur, ribs; head laceration **ID Number:** 2005102100319

Core Activity: Logging **Date of Accident:** 2005-Nov

Location: BC

Two vehicles, each occupied by one worker, were travelling in opposite directions on a forest service road when they collided. One worker (who was not wearing a seat belt) was injured.

Injury Type: Fatal (1 worker); minor injuries (1 worker) **ID Number:** 2005131490172

Core Activity: Integrated forestry management **Date of Accident:** 2005-Jul

Location: Central Interior

A pickup truck was descending a straight section of a gravel road. As it passed a loaded logging truck (travelling in the same direction), the pickup went out of control. It ran off the left side of the roadway and rolled onto its cab as it went down a steep 35-foot embankment.

Injury Type: Close Call **ID Number:** 2005137160196

Core Activity: Integrated logging **Date of Accident:** 2005-Jul

Location: Vancouver Island

A loaded off-road logging truck lost braking power while descending a steep logging road. The driver steered the truck into the ditch and managed to bring it to a complete stop without overturning the truck. The air supply for the braking system had not been completely built up before the truck descended the hill.

CONSTRUCTION

Injury Type: Fatal **ID Number:** 2006124490004

Core Activity: Land clearing construction **Date of Accident:** 2006-Jan

Location: Northern BC

A 3/4-ton pickup struck the side of a bed truck (oilfield heavy hauler) at a turn on a winter petroleum development road. The worker driving the pickup sustained fatal injuries; the driver of the bed truck was not injured.

Injury Type: Fatal **ID Number:** 2003070255

Core Activity: Logging road construction **Date of Accident:** 2003-Jun

Location: Vancouver Island

A rough terrain articulating dump truck loaded with rock was travelling down a steep grade. The driver was thrown from the vehicle when it crashed into the inside bank/ditch.

TRANSPORTATION AND WAREHOUSING

Injury Type: Crushing injuries **ID Number:** 2008153370075

Core Activity: Oilfield trucking **Date of Accident:** 2008-Mar

Location: Northern BC

An oilfield bed truck was towing a service rig pumper truck up a steep section of petroleum development road in slippery winter road conditions. However, the bed truck itself lost traction, and a young worker went to unhook the winch line connecting the two trucks. While the worker was between the trucks, the bed truck slid backwards, pinning the worker between the back of the bed truck and the front of the pumper truck.

Injury Type: Broken bones, lacerations (2 workers) **ID Number:** 2007140970257

Core Activity: Log hauling **Date of Accident:** 2007-Aug

Location: Northern BC

On a forest service road, an empty logging truck turned a corner and collided with a pickup truck. The worker driving the pickup truck was seriously injured.

SERVICE SECTOR

Injury Type: Fractured leg, cuts and bruises (1 worker); cuts and bruises (1 worker) **ID Number:** 2007158820167

Core Activity: Land surveying **Date of Accident:** 2007-Nov

Location: Northern BC

A 1-ton pickup truck struck the side of a 5-ton flat-deck truck. The collision occurred on a petroleum development road (PDR) at the bottom of a snow-covered hill. The two workers in the pickup suffered numerous cuts and bruises and one of them broke his leg.