

HAZARD ALERT


High-rise Construction

High winds blow out window

As a result of high winds, a window blew out of the 36th floor of a building under construction. The glass landed on the worksite below and in public areas near the site, causing a danger to workers, pedestrians and traffic. Fortunately, no one was injured. The window was cracked at the time of installation and had been taped as a temporary measure until it could be replaced.

Safe work practices:

- Ensure that defective or damaged windows are replaced immediately by a qualified contractor.
- Inspect all glass before installing.
- Never install defective, cracked or taped glass unless otherwise specified by the manufacturer.
- Maintain the worksite to ensure the health and safety of persons at or near the workplace.



WARNING
01-10